Reserve Disclosures

<u>Profile</u>

Name	Cypress HOA
Location	Cypress, CA 90630
Units/General Type	250 / Condominium
Base Year / Age	1965 / 46
Fiscal Year Ends	December-31

Parameters

Level of Service	Level 2 Reserve Study Update (With Site-Visit)
Prepared for Fiscal Year (FY)	2012
Most Recent On-Site Inspection Date	September 27, 2011
Allocation Increase Rate	ref Cash Flow Analysis
Contingency Rate	ref Component Details
Inflation Rate	3.0%
Interest Rate / Tax Rate	1.0% / 30.0%
Interest Rate (net effective)	0.7%
Current Reserve Allocation	\$266,800 per year
Current Reserve Balance	\$342,493 as of July 31, 2011
Funding Plan - Method / Goal	Cash Flow / Threshold - average Percent Funded 80%

<u>Summary</u>

FY Start Balance Fully Funded Balance	\$409,659 (projected to current FY end/nex \$1,189,044			(projected to current FY é	end/next FY start)
Percent Funded	34%	=			
Proposed Budget	per year	per month	per unit per month		
Reserve Allocation	\$230,381	\$19,198	\$76.79		

Association management/members need to understand that Percent Funded is a general indication of reserve strength and that the parameter fluctuates from year to year due to the Disbursement Schedule.

The Reserve Allocation was determined using the Funding Plan indicated above under the Parameters section. This allocation should be increased annually using the Allocation Increase Rate found in the Cash Flow Analysis.

Association management should budget the Reserve Allocation amount toward reserves for next fiscal year, to ensure the availability of reserves to fund future reserve component expenditures. This amount reflects a change of -13.65 % from the Current Reserve Allocation. The Reserve Allocation must be reviewed and adjusted for inflation (and other vital factors) in succeeding years to ensure the- Security of a Successful Plan!

	Reserve Component	Current Cost	Useful Life	Remaining Life
	Coat/Paint/Stain	******		
01.01	building exteriors,paint-A	\$110,250	7	6
01.02	building exteriors,paint-B	\$267,750	7	7
01.03	wrought iron,paint	\$7,718	4	1
02 E	Equipment			
02.01	deck,concrete repairs,pool areas	\$15,750	20	10
02.02	folding furniture,clubhouse #1	\$1,602	20	9
02.03	folding furniture,clubhouse #2	\$1,602	20	9
02.04	hvac,clubhouse #1	\$6,185	20	5
02.05	hvac,clubhouse #2	\$6,185	20	5
02.06	play equipment & surface	\$36,057	15	2
02.07	water heater, clubhouse #1	\$1,260	12	1
02.08	water heater, clubhouse #2	\$1,260	12	1
03 F	encing			
03.01	wood fence	\$10,500	20	9
03.02	wrought iron,pool #1,replace	\$8,400	20	5
03.03	wrought iron,pool #2,replace	\$8,400	20	5
03.04	wrought iron,pool #3,replace	\$8,400	20	5
04 F	Paint,Stain,Coating- 9009	n 19 Ann 20 m a Thair an Gan Gan an an ann an ann an ann ann		
04.01	carports,paint	\$44,625	6	4
05 F	Pools/Spas			
05.01	filter,pool #1	\$2,573	10	8
05.02	filter,pool #2	\$2,573	10	3
05.03	filter,pool #3	\$1,286	10	1
05.04	filter,wader #1	\$1,286	10	8
05.05	filter,wader #2	\$1,286	10	3
05.06	heater,pool #1	\$2,940	10	2
05.07	heater,pool #2	\$2,940	10	9
05.08	heater,pool #3	\$2,415	10	2
05.09	pumps,pools/waders	\$3,938	8	4
05.10	rehab,pool #1	\$12,600	12	10
05.11	rehab,pool #2	\$12,600	12	7
05.12	rehab,pool #3	\$8,883	12	11
05.13	rehab,wader #1	\$3,150	12	10
05.14	rehab,wader #2	\$3,150	10	7

Reserve Disclosures

	Reserve Component	Current Cost	Useful Life	Remaining Life
	Restoration		<u>8,7,8,0,7,0,2,2,2,2,5,5,0,0,0,7,0,0,0,000</u>	**********
6.01	bathrooms,clubhouse #1	\$2,625	12	3
6.02	bathrooms,clubhouse #2	\$2,625	12	3
6.03	bathrooms,pool area #3	\$2,625	12	3
6.04	carports,rehab-unfunded	\$0	999	999
6.05	clubhouse #1,rehab	\$12,810	15	1
6.06	clubhouse #2,rehab	\$12,810	15	1
6.07	concrete, repairs	\$5,250	4	2
6.08	irrigation system,rehab	\$105,000	20	4
	Roofs			
7.01	flat roofs-02	\$10,500	25	7
7.02	flat roofs-06	\$31,500	25	10
7.03	flat roofs-07	\$36,750	25	20
7.04	flat roofs-11	\$57,750	25	8
7.05	flat roofs-12	\$63,000	25	16
7.06	flat roofs-13(a)	\$68,250	25	15
7.07	flat roofs-13(b)	\$68,250	25	21
7.08	flat roofs-22	\$115,500	25	17
7.09	flat roofs-23	\$120,750	25	1
7.10	flat roofs-24	\$126,000	25	18
7.11	flat roofs-26	\$136,500	25	19
7.12	flat roofs-27	\$141,750	25	24
7.13	flat roofs-29	\$152,250	25	11
7.14	flat roofs-40	\$210,000	25	22
7.15	mansard roofs-2000	\$21,105	50	39
7.16	mansard roofs-2001	\$73,868	50	40
7.17	mansard roofs-2002	\$63,315	50	41
7.18	mansard roofs-2003	\$70,350	50	42
7.19	mansard roofs-2004	\$66,833	50	43
7.20	mansard roofs-2005	\$49,245	50	44
7.21	mansard roofs-2006	\$91,455	50	45
7.22	mansard roofs-2007	\$70,350	50	46
7.23	mansard roofs-2008	\$73,868	50	47
7.24	mansard roofs-2009	\$66,833	50	48
7.25	mansard roofs-2010	\$28,140	50	49
7.26	mansard roofs-2011	\$10,553	50	50
7.27	mansard roofs-2012	\$87,938	50	1

Reserve Disclosures

•

ID:1852- Cypress HOA JN:4396-C-2 Strategic Reserves Corporation November 09, 2011

Reserve Component	Current Cost	Useful Life	Remaining Life
07 Roofs 07.28 mansard roofs-2013	\$116,078	50	2
Grand Total: 66	\$2,969,990		

.

Reserve Disclosures