EXECUTIVE SUMMARY

RESERVE ANALYSIS

CURREDO HOME OURIERO (CO.	DECE	DECEMBER 31, 2008				
CYPRESS HOME OWNERS ASSO	CURRENT REPLACEMENT	REMAINING LIFE	USEFUL LIFE	PROJECTED RESERVES 12/31/08	MONTHLY FUNDING REQUIREMENT	IDEAL RESERVE
COMPONENT	COST	LIFE	LIFE	12/31/00	KLQ OTKLIILIVI	TUSERIE
BUILDING ELEM	IEN1S					
ROOFING COMPONENTS; Tile Mansards	\$541,800	25	30	\$1,320	\$1,801.58	\$90,300
Wood Mansards	361,200	4	30	4,574	7,429.67	313,040
Flat Roofs	150,000	15	15	0	833.33	0
Flat Roofs	1,350,000	8	15	9,206	13,966.58	630,000
Flat Roofs	375,000	1	15	5,115	30,823.75	350,000
Carport Roofs	495,000	14	25	3,183	2,927.50	217,800
SIDING REPLACEMENT;						
Wood Siding	252,840	10	30	2,463	2,086.50	168,560
OTHER;						
Termite Control-Fumigation	3,000	7	15	23	35.42	1,600
Wood Repairs	50,000	2	10	585	2,059.00	40,000
						04.044.200
Category Total	\$3,578,840			\$26,469	61,963.33	\$1,811,300
FENCES & GA	<u>TES</u>					
WROUGHT IRON;						
Pool Fence	20,000	1	20	20,000	0.00	19,000
Pool Fence	40,000	. 3	20	497	1,097.33	34,000
				000.405	1 005 22	652 000
Category Total	\$60,000			\$20,497	1,097.33	\$53,000
PAINT						
EXTERIOR SURFACES;						
Phase 1	62,980	1	5	62,980		50,384
Phase 2	62,980	2	5	552	,	37,788
Phase 3	62,980	3	5	368	· ·	25,192
Phase 4	62,980	4	5	184	,	12,596
Phase 5	62,980	5	5	0	1,049.67	U
WROUGHT IRON;			_		0.00	4.550
Pool Fences	7,125	1	3	7,125	0.00	4,750
OTHER PAINTING;						0.50
Clubhouse Interiors	1,700	3	6	12		850
Carports	25,500	10	10	0	212.50	0
				\$71,222	6,957.76	\$131,560
Category Total	\$349,225			\$ / 1,222	0,737.70	\$151,500
IRRIGATIO	N					
SYSTEM COMPONENTS;					0.00	22.665
System Upgrade	35,000	1	15	35,000	0.00	32,667
	025.000			\$35,000	0.00	\$32,667
Category Total	\$35,000			\$55,000	0.00	Ψ52,007
POOLS/WADE	ERS					
COMPONENTS & EQUIPMENT	; ;					
Pool #1 - Plaster & Tile	14,750	12	12	0		0
Pool #1 - Gas Heater	3,200	1	12	3,200		2,933
Pool #1 - Filter	1,350	9	12	5 0		338 0
Wader #1 - Plaster & Tile	8,250	12	12 12	5		313
Wader #1 - Filter	1,250	9 8	12	72		4,917
Pool #2 - Plaster & Tile	14,750 3,200	8 1	12	3,200		2,933
Pool #2 - Gas Heater	1,350	9	12	5,200		338
Pool #2 - Filter Pool #3 - Plaster & Tile	14,750	8	12	72		4,917
Pool #3 - Plaster & The	3,200	1	12	3,200		2,933
Pool #3 - Filter	1,350	1	12	1,350		1,238
1 001 110 - 1 11001	1,230	-		*		

EXECUTIVE SUMMARY

RESERVE ANALYSIS

CYPRESS HOME OWNERS ASSO	С.					MBER 31, 2008
	CURRENT			PROJECTED	MONTHLY	
	REPLACEMENT	REMAINING	USEFUL	RESERVES	FUNDING	IDEAL
COMPONENT	COST	LIFE	LIFE	12/31/08	REQUIREMENT	RESERVE
	0.250	0	12	40	85.50	2,750
Vader #2 - Plaster & Tile	8,250	8 . 1	12	1,250	0.00	1,14
Vader #2 - Filter	1,250		5	32	151.92	2,20
umps & Motors	5,500	3	5	18	82.83	1,20
ncidentals	3,000	3	4	12	89.92	81
Mastic	3,250	3	25	438	413.00	30,00
Deck Reserve	50,000	10	25	430	415.00	30,00
RELATED ELEMENTS;					4 6 4 7 70	24.66
ot Lot Equipment	40,000	2	15	507	1,645.58	34,66
Category Total	\$178,650			\$13,405	2,970.68	\$93,636
RECREATION RO	<u>OMS</u>					
CLUBHOUSE CONTENTS;						
HVAC Systems	6,500	7	25	68	76.58	4,68
Appliances	3,500	10	20	26	28.92	1,75
Furnishings	5,000	5	10	37	82.75	2,50
Floors	6,000	7	15	47	70.83	3,20
Remodel	9,000	13	25	63	57.25	4,32
Category Total	\$30,000			\$240	316.33	\$16,45
<u>other</u>						
SIGNS;						
Common Area Signage	4,000	4	8	. 29	82.75	2,00
	.,					
COMMON AREA;	27,000	2	15	342	1,110.75	23,40
Frash Access Gates		5	15	40		2,75
Wood Benches	4,125	1	1	36,102	0.00	36,10
Contingency (5%)	36,102	1	1	50,102	0.00	
Category Total	\$71,227			\$36,513	1,261.58	\$64,25
CRAND TOTAL C.	\$4,302,942			\$203,346	\$74,567.01	\$2,202,86
GRAND TOTALS:	54,302,942			\$200,010	•	
Less Projected Available Reserves						203,34
Ideal Reserve Deficiency (Over Fu	inding)*					\$1,999,51
Percent Funded To Ideal Reserve						9

^{*}A positive result indicates an Ideal Reserve Deficiency while a (negative balance) reflects an Over Funded Condition.

NOTE: Monthly Funding Requirement is predicated on the Current Reserve Method of funding.

NOTE: This schedule reflects summary data only, for supporting details and/or additional information please refer to the complete Reserve Study Report

^{**} Assumes uniform assessment per ownership, if assessments vary by size or type of ownership interest see attached schedule